ASK 21



Flight Manual

F-CJEM

	CHER SEGELFLUGZEUGBAU n/ Wasserkuppe, West German
FLIG	HT MANUAL
for the	sailplane model
A ==	SK 21
This manual must a	lways be carried on board
It belongs to the	sailplane ASK 21
Variant	Data Sheet no.339
	2439
Registration no.	F-CJEM
Owner :	AAVA
	• • • • • • • • • • • • • • • • • • • •
	•••••
Manufacturer :	Alexander Schleicher Segelflugzeugbau
	6416 Poppenhausen/ Wasse West Germany
ginal which is app of Civil Aeronauti as operating instr	translation of the German roved by the LBA (Federal cs of the Fed.Rep. of Germ uctions according to para n 'LuftGerPO' (Aviation Eq ons).

.

Annexe 1



Cet intercalaire doit obligatoirement être inséré devant la page de garde d'un manuel de vol en langue anglaise

AVERTISSEMENT

Le présent document en langue anglaise est le manuel de vol approuvé par l'Agence européenne de la sécurité aérienne.

En application des dispositions de l'arrêté du 24 juillet 1991 relatif aux conditions d'utilisation des aéronefs civils en aviation générale (« Un vol ne peut être entrepris que si, d'une part les membres d'équipage sont familiarisés avec l'aéronef et son équipement de bord, notamment le matériel de sécurité-sauvetage et les systèmes spéciaux, et d'autre part ont une connaissance pratique de son manuel de vol ou des documents acceptés comme équivalents. »),

Nul ne peut utiliser l'aéronef avec ce seul document s'il n'a pas une connaissance suffisante de la langue anglaise.

A défaut, il appartient au propriétaire ou à l'exploitant de l'aéronef de se procurer une traduction de ce document sous sa responsabilité.

Référence : Instruction du 13/11/2009 relative à la langue des manuels de vol



Check List / 1

Pre Flight Check

- 1. Main pins secured ?
- 2. Rear wing attachment pins: is the safety lock visible above the pin ?
- 3. Horizontal tail unit pins secured. Is the spring retainer engaged ?
- 4. Elevator pushrod connected ? Secured with a spring clip ? This is not applicable for gliders which use the automatic elevator connection !
- 5. Aileron pushrods connected ? Secured with a spring clip ? Do not forget the sight control through the access hole cover !
- 6. Airbrake pushrods connected ? Secured with a spring clip ? Do not forget the sight control through the access hole cover !
- 7. TM 25 / TM 30:

Are the rudder cables connected to the joint between both seats and secured according to the rules resp. disconnected and attached to the anchor points ?

Is the plug-in rudder hand lever secured ?

Function of the rudder control in both seats checked ?

Cable tension of the rudder hand control system checked ?

8. Check for foreign bodies!

Attention !

With all L'HOTELLIER quick-release joints one must be able to touch the ball pivot by feeling through the slot in the ball socket. Check the proper engagement of the safety lock by pushing it on to close!

TN 20 16.10.87 TN 38 May 2016	P. Anklam	Page No.

CHECK LIST / 2

Pre take off check

- 1. Parachute connected to harness ?
- 2. Safety harness fastened ?
- 3. Airbrakes locked ?
- 4. Trim lever adjusted to a middle position ?
- 5. Altimeter adjusted ?
- 6. Canopies closed and locked ? Rear canopy !!
- 7. For flight with only one occupant remove rear back rest !!
- 8. Put your toes <u>under</u> the toe-straps !! Do not flatten the straps !! Danger of jamming the pedals !!

April 1980

I.1 Amendments record

Davi		·			Dete
Rev.	Title		Page		Date
No.	weak link in townone		12		Signature
	weak link in towrope,		12		15.04.82
2	weak link in towrope, Automatic elevator C				16.05.8
3	TN-No. 11	onnection,	36 a, 36 b, Checklist /		20.11.83
4	Modification of the Fl	ight Manual	10 b	1	23.02.84
-	TN-No. 13	igni manuai,			Z0.02.04
5	Amendment of the F	light Manual,	10 c		04.06.84
	TN-No. 13 a		10 b delete	ed	ノーショ
6	New canopy locking	system,	16 a, 17 a,		08.06.84
	TN-No. 15		18 a & 19		<u>م</u> ے
7	Change / supplemen	t to the Flight	Checklist /		03.11,87
	Manual, TN-No. 20		<u>36 a, 36 b</u>	<u>& 37</u>	قشر
8	New production serie		Annex	•	17.08,90
}	couplings for aerotov	v and winch			J=0
	launch, TN-No. 21			07.1	00.11.00
9	Checking and exchange		36 b, 37 a,	37 D	26.11,90
	rocker at the elevator	r actuator rod,			0
10	TN-No. 22 Revision of the Flight	Manual	13, 15, 25,	26	15.04.91
	TN-No. 23	l ivianual,	13, 15, 25,	20	15.04.91
11	Rudder actuated by r	means of hand	16a & 21		17.06.93
	lever, TN-No. 25 (op				
12	AD 93-001/2/3, L'Ho		Annex		27.04.98
	for the maintenance,	Rev. E 03/94			ه ال
13	Extension of service		43f		04.05.06
	operation hours, TN	No. 29			mm
		1			
			1		
1					
	ļ				1
Rev	no. / Date Sig.	Author D	ate	Page n	
1.01.			pril 80		2
				LBA-ane	

Amendments record

		<u> </u>			
Rev.	Title			Page	Date
No.					Signature
Rev.	no. / Date	Sig.	Author Kaiser	Date April 80	Page no.
			Naissi	April 00	2 a

	-	ASK 21 - Flight Manual	
	I.2 C	DNTENTS	Page
	I.	General	1
	I.1	Amendments record	2
	1.2	Contents	3 + 4
	I.3	Description	1 2 3 + 4 5
	II.	Operating limitations	6
	II.1	Airworthiness category	6
	II.2	Operation range classes	6
	II.3	Equipment	7 8
	II.4	Speeds	
	11.5	Load factors	9
	11.6	Weights	9
	II.7	In flight c.g.	10
	II.8	Weight and balance information	10
	II.9	Tow releases	12
	11.10	Weak link in tow rope	12
		Tire pressure	12
	II.12	Cross wind	12
	III.	Emergency procedures	13
	III.1	Recovery from spins	13
	III.2	Canopy emergency jettisoning and	
		emergency bail out	13
	III.3		14
		Wing dropping	15
	III . 5	Ground looping	15
	IV.	Normal operation procedures	16
	IV.1	Cockpit and operating levers	16 - 20
	IV.2	Daily checks	21
	IV.3	Pre take off check	23
	IV.4	Take off	24
	IV.5	Free flight	25
	IV.6	Low speed flight and wing dropping	
	IV.7	High speed flight	26
	IV.8	Cloud flying	26
	IV.9	Aerobatics	27 - 34
	IV.10	Approach and landing	35
	۷.	Rigging and derigging	36
	V. 1	Rigging	36
3		April 1980	3

ASK 21 - Flight Manual				
٧.2	Derigging	37		
V.3	Parking	37		
V.4	Road Transport	37		
۷.5	Preventive maintenance	37 38		
	Airspeed position error	3 9		
	Speed polar	40		
	Lubrication scheme	41		

I.3 DESCRIPTION

The ASK 21 is a two-seater sailplane with T-tail, fixed nose wheel and dive brakes on upper wing. The main landing gear is sprung.

The sailplane is built in FRP-sandwich-monocoque construction. It may be used for school and high performance flights as well as for aerobatics of the Airworthiness Category 'A'.

Technical Data

Span	17.00 🖬	(55,74 ft)
Length	8,35 m	(27,38 ft)
Height	1,55 m	(5,08 ft)
Wing area	17,95 m ²	(192,95 sq.ft)
Aspect ratio	16,1	
Max all-up weight	600 kg	(1320 lbs)
Max wing loading	33,4kg/H ²	(6,84 1bs/sq.ft)

II. OPERATING LIMITATIONS

II.1 AIRWORTHINESS CATEGORY

Basis of the type-approval are the Airworthiness Requirements for Sailplanes and Powered Sailplanes (LFSM), issue Oct. 23, 1975, with the Airworthiness Category 'A' (Acrobatic).

II.2 OPERATION RANGE CLASSES

The operation range classes approved for the particular sailplane are indicated by a data placard on the instrument panel (see Maintenance Manual page). Depending on the respective equipment the sailplane may be licensed for traffic for the following operation range classes :

- 1. Airworthiness Category 'U' (UTILITY)
 - According to VFR (during daylight) with equipment as per II.3 a.
 - b. Cloud flights with equipment as per II.3 a and II.3 c.

2. Airworthiness Category 'A' (Acrobatic) - with equipment as per II.3 a and II.3 b or II.3 a, II.3 b and II.3 c for the following aerobatics :

> Loop, Stall Turn, Split 'S', Immelmann, Slow Roll, Inverted Flights, Spin, Steep ClimbingTurn, Lazy Eight, Chandelle.

6

II.	3 EQUIPMENT
a.	Min. equipment
	 Airspeed indicator up to 300 km/h Altimeter Four-piece safety harness for front and rear seat Seat cushions, at least 10cm thick when
	<pre>loaded, or parachutes (automatic or manual) 5. Weight and balance data placard (front and rear seat)</pre>
	6. Data plate 7. Flight Manual
Ъ.	Equipment for aerobatics
	For aerobatics the above min. equipment must be supplemented as follows :
	 Additional bottom strap for the safety harness G-meter for front seat
	 G-meter for front seat Foot loops on rudder pedals Parachute (automatic or manual)
c.	Equipment for cloud flying
	For cloud flying the above min. equipment must be supplemented as follows :
	 Variometer Turn and bank indicator Magnetic compass (compensated) VEF transceiver radio
	April 1980 7

<u>
</u>

	ASK 21 - Flight Manual					
II.4 SPEED	S					
Max speed cal	m air	V _{NR} :	-•)280) icm/h	(15	1 kts)
Max speed rou;	gh air	V _B	= 200) km/h	(108	3 kts)
Max maneuveri:	ng speed		= 180) km/h	(97	7 kts)
Max speed aer	otow	••) km/h		
Max speed wind	ch tow	v,	15 0	km/h	(81	1 kts)
Rough air mean Cn-clouds, dua creats.	st devils	, or wi	nen sl	cimmin;	g mour	ntain
Maneuvering sp full control of	peed V _M i deflectio	s the ons sti	highe	est spa Ly be a	eed at applie	t which ed.
With max speed V _{NE} only one third of the max pos- sible deflections may be applied. One must also take into account that with increasing altitude the true airspeed is higher than the reading of the A.S.I. because of the decreasing air density. True airspeed (TAS) is, however, relevant for safe- ty against flutter. *) The max indicated V _{NE} is reduced as follows ac-						
ty against fluThe max inc	utter. dicated V					
 ty against flu The max incording to all 	utter. dicated V titude :	NE is	reduc	as be:	folld	
ty against fluThe max inc	utter. dicated V titude :		reduc	ed as	follo 5000	
 ty against flu The max incording to all 	dicated V titude : (M)	NE is	reduc	as be:	follo 5000	6000
ty against flu *) The max incording to alto Altitude	utter. dicated V titude : (M) (km/h)	NE ¹⁸ 0-2000	reduc 3000 267	4000 255	folla 5000 239	6000 226
<pre>ty against flu *) The max inc cording to ald Altitude V_{NE} indicated</pre>	utter. dicated V titude : (M) (km/h) (ft)	NE ^{is} 0-2000 280	reduc 3000 267	4000 255	folla 5000 239	6000 226
ty against flu *) The max incording to all Altitude V _{NE} indicated Altitude	utter. dicated V titude : (M) (km/h) (ft)	NE ¹ 5 0-2000 280 5000 1	reduc 3000 267	ed as 4000 255 15000	folla 5000 239 20000	6000 226

The airspeed indicator must show the following color codes : 80-180 km/h (43 - 97 kts)Green arc 180-280 km/h (97-151 kts)Yellow arc Red radial line at 280 km/h (at 151 kts) Yellow triangle at 90 km/h (at 48.5 kts) II.5 LOAD FACTORS The following load factors must not be exceeded : +6.5 at maneuvering speed V_M -4.0 VNE at max speed +5.3 -3.0 with airbrakes extended +3.5 + 0 G-meter markings : a. positive range yellow arc +5,3 to +6,5 red radial line at +6.5b. negative range yellow arc -3.0 to -4.0 red radial line at -4.0**II.6** VEIGHTS approx. 360kg Empty weight $(792 \, 1bs)$ Max all-up weight 600kg (1320 lbs) Max weight of non lift 410kg (904 1bs) producing members

II.7 IN FLIGHT C.G.

The in flight c.g. range is from 234mm to 469mm behind datum (9,21" to 18,46"); correspondingly 20,2 % up to 41,1 % of the mean aerodynamic chord,

t = 1,121m (3'68'') with a = 8mm (0,32'') behind wing leading edge; inner wing = datum point.

11.8 WEIGHT AND BALANCE INFORMATION

Min payload front seat	70 kg	(154 lbs)
Max payload front seat	110 kg	(242 1 bs)
Max payload rear seat	110kg	(242 1bs)
Baggage in wingroots max	2 x 10kg	(2 x 22 1bs)

Neither the all up weight of 600kg (1320 lbs) nor the max weight of non-lift producing members + occupants & baggage of 410kg (904 lbs) must be exceeded.

The weight limitations on the basis of the last weighing are to be found on page 11 1

With this loading the in flight c.g. is in the permissible range.

Low weight in the front seat must be compensated by fixed ballast.

II.8 cont. Weight and Balance Information / Minimum load in front seat

The minimum payload in the front is found on the weight and balance sheet on page 11.

CAUTION: Short weight in the front seat must be compensated by ballast (installation of lead discs in the nose). 1 lead disc = 2.76 lbs pilot weight

	Results in a reduction of If the minimum payload					
Number of	the minimum payload in		the front seat is 70kg			
lead discs	the front seat of		(154lbs), it changes to:			
	kg	lbs	kg	lbs		
0	0	0.00	70	154.32		
1	1.25	2.76	68.75	151.57		
2	2.5	5.51	67.5	148.81		
3	3.75	8.27	66.25	146.06		
4	5	11.02	65	143.30		
5	6.25	13.78	63.75	140.54		
6	7.5	16.53	62.5	137.79		
7	8.75	19.29	61.25	135.03		
8	10	22.05	60	132.28		
9	11.25	24.80	58.75	129.52		
10	12.5	27.56	57.5	126.77		
11	13.75	30.31	56.25	124.01		
12	15	33.07	55	121.25		

Concerning the minimum payload in the front seat, in addition the following applies: One third of the weight of the rear pilot contributes to the payload in the front seat.

But for pilot training it may be noted: If from the beginning the student forms a habit of installing the amount of lead discs he would also need for solo flying, fewer mishaps may arise later.

II. WEIGHT & BALANCE INFORMATION

- Max. payload front seat (pilot incl. parachute): 242 lbs = 110 kg
- Min. payload front seat (pilot incl. parachute): 154 lbs = 70 kg

Caution: Short weight in the front seat must be compensated by ballast (installation of lead discs in the nose; 1 lead disc = 2,76 lbs pilot weight).

Number of lead discs	Min. payload kg	front seat lbs
0	70,0	154,32
1	68,75	151,57
2	67,5	148,81
3	66,25	146,06
4	65,0	143,30
5	63,75	140,54
6	62,5	137,79
7	61,25	135,03
8	60,0	132,28
9	58,75	129,52
10	57,5	126,77
11	56,25	124,01
12	55,0	121 ,25

Max. payload rear seat (pilot incl. parachute): 242 lbs = 110 kg.

1 kg = 2,2046223 lbs

11	Date of weight & balance	Empty weight c.g. (mm/in. behind datum)	Front se payload min	at kg/lbs incl.chute max	payload :	t kg/lbs incl.chute max	Signature of inspector, inspection stamp	
								ASK
April								21 -
1980								Flight Manual
								ual
11								

II.9 TOW RELEASES

For aerotow : nose release E 75 For winch tow : safety release Europa G 73

II.10 WEAK LINK IN TOW ROPE Aerotow max. 600 ± 60 daN Winch tow max. 1000 ± 100 daN

II.11 TIRE PRESSURE Main wheel 5.00-5 : 2,7 bar Nose wheel 4.00-4 : 2,0 bar Tail wheel 210×65 2,5 bar

II.12 CROSSWIND

The permissible crosswind component is about 15 km/h. (8 knots).

III. EMERGENCY PROCEDURES

III.1 RECOVERY FROM SPIN

According to the standard procedure spinning is terminated as follows:

- 1. Apply opposite rudder (i.e. apply rudder against the direction of rotation of the spin).
- 2. Short pause (hold control inputs for about 1/2 spin turn).

Warning: Disregarding the pause will result in slower recovery!

3. Release stick (i.e. give in to the pressure of the stick) until the rotation stops and sound airflow is established again.

Warning: Full forward stick may retard or even prevent the recovery!

- 4. Centralise rudder and allow sailplane to dive out. The altitude loss from the beginning of the recovery until the normal flight attitude is regained is about 80 meter (260 feet).
- Note: During spins the ASK 21 oscillates in pitch. From a steep nose down spin recovery according to the standard procedure is up to 1 turn, from a flat spin less than 1 turn.

III.2 CANOPY JETTISONING AND EMERGENCY BAIL OUT

- <u>Front canopy:</u> a. Move lever with red knob above the instrument panel to the left and push canopy upwards.
 - b. Open safety harness.
 - c. Get up and bail out.
 - d. With manual chute seize release grip and pull out entirely after 1 to 3 seconds.

Rev.no./Date Sig.	Author	Date	Page no.
Rev.no./Date Sig. TN23 Jan.91 Waibel	Kaiser	April 80	Pageno. LBA- 13 App.

Rear canopy : a. Pull back both canopy side locks and push canopy upwards. b. Open safety harness. c. Get up and bail out. d. With manual chute seize release grip and pull out entirely after 1-3 seconds. If circumstances allow, the front pilot should allow the rear pilot to bail out first. III.3 FLIGHTS IN THE RAIN With wet or alightly iced wings or insect accumulation there will be no deterioration in flight characteristics. However, one has to reckon with a rather considerable deterioration in flight performance. This must be taken into account especially on landing final approach !! Add a safety margin of 10 km/h (5,4 knots) for approach speed 11

III.4 WING DROPPING

The sailplane stalls extremely benign. Nevertheless one always has to face the possibility of wing dropping because of turbulence. In that case push stick forward immediately and apply opposite rudder against a noticeable turn <u>at the same time</u> to regain a normal flight attitude. If the rudder deflection against the turn is forgotten, a spin may occur even if the stick pressure is released.

III.5 GROUND LOOPING

For normal conditions, smooth runway, short grass, one may take off with the wing on the ground without having to fear a change in the direction.

High grass and rough ground, however, may cause ground looping. In that case release the tow rope immediately.

Rev.no./Date Sig.	Author	Date	Page no.
Rev.no./Date Sig. TN23 Jan.91 Waibel	Kaiser	April 80	LBA- 15 App.

IV. Normal Operation procedures


IV.1 Cockpit and operating levers

Front seat:

- 1. Stick
- 2. Trim; flat lever with green knob LH of stick.
- 3. Rudder pedal adjustment; grey knob at the console
- 4. Airbrakes with wheel brake; **blue** hand grip in the left lever arm rest
- 5. Release cable; **yellow** knob on the front left below the canopy frame
- 6. Canopy emergency jettisoning; horizontal lever with **red** flat knob above the instrument panel cover. To the left = "Open".
- 7. Front canopy locking; white swivel levers forwards - parallel to the canopy frame.
- Ventilation nozzle; on right cockpit wall below canopy frame; ad-8. justable and closable.
- 9. Back rest; the back rest is adjustable by lifting it at the bottom upwards and forwards (see sketch). In normal flight attitudes the backrest cannot shift by itself. Very tall pilots may fly without the back rest.
- 10. Trim indicator; in the right arm rest behind the ventilation nozzle.
- 11. Detachable rudder hand lever at the left cockpit wall below the airbrake grip (not shown). Only applicable for mod. TN No. 25 and TN No. 30.

Sig.

JUW




Rear seat:

- 1. Stick
- 2. Trim; flat lever with green knob LH of stick.
- 3. Rudder pedal adjustment with circular grip in front of stick.
- 4. Airbrakes with wheel brake; **blue** lever in the left arm rest.
- 5. Release cable; **<u>yellow</u>** knob on left cockpit wall below the canopy frame
- Rear canopy locking = Canopy <u>emergency</u> jettisoning;
 <u>Red</u> swivel levers on left and right canopy frame.
 To open canopy: pull <u>back</u> both levers.
 To lock canopy: push both levers <u>forwards</u>, parallel to the canopy frame.
- 7. Ventilation nozzle; on right cockpit wall below the canopy frame; revolving and lockable.
- Back rest; the back rest is adjustable by tilting it from the bottom upwards and forwards (see sketch); in normal flight attitudes the backrest cannot shift by itself.
 <u>Attention:</u> At flights with one pilot the rear backrest must be fixed with the safety harness.

Very tall pilots may fly without the back rest.


- 9. Trim indicator; in the right arm rest behind the ventilation nozzle.
- 10. Detachable rudder hand lever at the left cockpit wall below the airbrake grip (not shown). Only applicable for mod. TN No. 30.



Connection of the rudder pedals:

The rudder control with a hand lever enables pilots to fly the ASK 21, even when their capability to move their legs is limited. In this case the feet resting on the pedals must not obstruct the rudder. Therefore, the cables coming from the particular pedals can be disconnected at the joint between the front and rear seat. The disconnected cables have to be fixed on special anchor points on the fuselage wall.

Cable connection of the left side is pictured:



Anchor point for disconnected cable of the front pedal.

Connection plate for cables of rudder pedals with lock washer for connection bolts.

Anchor point for disconnected cable of the rear pedal.




Connection plate for cables of rudder pedals with demounted lock washer. The removable connection bolts are visible.

Attention: The position of the connection bolts in the row of holes must be marked, to avoid a change of the total cable length

when reconnecting, which would result in a change of the pedal position. The holes not needed will already be closed ex works.

Rev.No) . /	Date
TN 38	Ma	y 2016

Possible Variants:



Front and rear pedals connected

Attention:

The lock washer must be mounted according to the rules to hold the connection bolts in their position.

The screws of the anchor points for the disconnected cables must be removed!



Rear pedals disconnected

Attention:

The towing ropes of the **rear** pedals have to be attached with screws left and right at the **lower** anchor points.

Likewise also only the **front** pedals can be disconnected and have to be fixed on the **upper** anchor points.




Front and rear pedals disconnected

In this situation, the rudder can in both pilot seats only be controlled with a hand lever.

Rev.No. / Date TN 38 May 2016 Sig. P. Anklam

19c

Checking and Adjusting of the Cable Tension:




The adjusting screw for the cable tension of the rudder hand control system is located in the front of the control column and besides of the pedal adjustment. This is for the **fine adjustment** of the cable tension during the Pre Flight Check.

Shifting in the direction of flight results in a higher cable tension, shifting against a lower. After the adjustment both knurled nuts have to lock the part between again.

The cable tension is high enough, if the hand lever has no noticeable play with blocked rudder. The cable tension is too high, if the rudder does not move freely.


If the adjusting screw allows no correct adjustment of the cable tension, the system has to be maintained. It has to be adjusted and inspected



as follows:

- Remove the front fairings covering the swing lever.
- Adjust the cable tension by readjusting the cable mounting points on connection plates left and right on the swing lever.
- Check freedom from play and free movement.

Rev.No	b . /	Date
TN 38	Mag	y 2016



IV.2 Daily Checks

- 1 a) Open canopy! Check that the main pins are properly secured by the lock catches.
- b) Check the proper connection of the ailerons and airbrakes through the access hole on the left side above the wing. Are the quick-release connectors secured with spring clips ?
- c) Check for foreign bodies !
- d) Check the control circuits force and that all controls are free-moving. Apply full deflections and load the control circuits with fixed controls and airbrakes. Check the plastic tubes inside the s-shaped tubes of the rudder pedals for proper and tight fit.
- e) Check tire pressure ! Nose wheel 2.0 bar (28 psi) Main wheel 2.7 bar (38 psi) Tail wheel 2.5 bar (35.6 psi) (if installed).
- f) The condition and function of the tow release mechanism is to be checked. Actuate the tow release: does it snap back freely? Engage and disengage the ring pair. Check the automatic re-lease of the C.G. towing hook with the ring pair which must re-lease automatically backwards.
- g) Check the wheel brake. Pull the air brake lever; at the end of its travel and elastic resistance must be felt.
- h) Check cable tension of the rudder hand control system (see page 19.1a).


Only in flight operation with the rudder hand lever:

- Locking bolt screwed in at the airbrake handle and secured ?
- Rudder hand lever mounted and secured ?
- Are the rudder cables connected to the joint between both seats and secured resp. disconnected and attached to the anchor points ? (only TN 30)

Only in flight operation without rudder hand lever:

- Are the rudder cables connected to the joint between both seats and secured according to the rules ? (only TN 30)
- 2 a) Check upper & lower wing surface for damages !
- b) Aileron: condition, freedom of movement, and play is to be checked ! Check also the push rod connection.
- c) Airbrake: check condition, adjustment and good locking.
- 3) Check the whole fuselage for damages, in particular the bottom side.
- 4) Check that the tailplane is properly assembled and secured. Check also the pushrod connection. Secured by spring clips ?

Rev.No. / Date Sig. TN 38 May 2016 P. Anklam	Author Kaiser	Date April 80	Page No.	21
---	------------------	------------------	----------	----



- 5. Check condition of tailskid, pitot tube and venturi tube !
- 6. Check static vents for cleanness !
- 7. See 2.

After rough landings or excessive flight stress the whole sailplane must be checked with the wings and tail unit removed. If any damage is found, a technical inspector must be called in. On no account one must take off again before the damage has been repaired.

See also Maintenance Manual 11

- IV.3 PRE TAKE OFF CHECK
- 1. Controls easy to operate ?? (Control circuits check done ??)
- 2. Airbrakes locked ??
- 3. Trim neutral ??
- 4. Canopy locked ?? Pay especially attention to the rear canopy !
- 5. Safety harness and parachute fastened ?? (Parachute static line engaged with automatic parachute ??)
- 6. Altimeter adjusted to field height or to zero ??
- 7. Radio "on" and adjusted to proper frequency ??

ASK 21 - Flight Manual IV.4 TAKE OFF Winch tow : Trim neutral. Max two speed : 150 km/h (81 kts). The sailplane features a tow release for winch tow in front of the main wheel. The most favorable tow speed is 90 - 110 km/h (49) 60 kts). There is little pitch up tendency during the initial tow. In the upper third of the tow additional altitude may be gained by slight back pressure. Toy release : pull the release knob to the stop several times. Aero tow : Aero tows only with the nose release in front of the nose wheel. Recommended tow rope length : 30-60 m (98-197 ft); textile rope. Trim neutral. Max tow speed : 180 km/h (97 kts). The most favorable tow speed during climb is 90 -140 km/h (49 - 76 kts). Take off may be done with the wingtip on the ground. Getting the wings level is no problem. However, the pilot is advised to be careful with high grass and very rough ground. Take off takes place at about 75 km/h (40 kts).

IV.5 FREE FLIGHT

The sailplane may be flown up to V_{NE} = 280 km/h (151 kts), see p.8. Up to manoeuvring speed of 180 km/h (97 kts) full control deflections can be applied. At higher speeds the controls must be applied more carefully.

At V_{NE} only 1/3 of the max. possible deflections must be applied.

IV.6 LOW SPEED FLIGHT, WING DROPPING AND SPINS

With the stick back a distinct tail buffet is felt.

The sailplane is very benign in low speed flight. By use of normal aileron deflections the wings may be kept level down to minimum speed, even with aft C.ofG.-positions.

With normal rudder deflections no wing dropping is found. Yaw angles of up to 5° have no significant influence on the wing dropping attitude.

Also rapid pulling up into 30° pitch does not cause wing dropping, but only a gentle nose drop. The same applies for stalling out of a 45° turn.

But one has to point out that even the most benign sailplane needs speed in order to be controllable.

In turbulence this is especially important when also a wing dropping may occur.

Spin developement from wing dropping strongly depends on the C.ofG. position and also to some extent from the pilot reaction.

For C.ofG.positions forward of 315 mm aft of datum the ASK 21 does not spin at all. This configuration applies to 2 heavy pilots.

For C.ofG.-positions from 320 mm through 385 mm aft of datum, more incipient spin turns are possible followed by self recovery after 4 1/2 turns at most. Such C.ofG.-positions are possible in dual flight with a lightweight pilot in the front seat.

For C.ofG.-positions aft of 400 mm behind datum controlable sustained spins are possible. Such a C.ofG.-position is usually only possible with one lightweight pilot in the front seat.

Rev.no./Date Sig.	Author	Date	Page no. LBA- 25
TN23 Jan.91 Waibel	Kaiser		LBA- 25 App.

Note: During spins the ASK 21 oscillates in pitch. From a steep nose down spin recovery according to the standard procedure is up to 1 turn, from a flat spin less than 1 turn.

The speed at which the stall takes place depends on the payload. The following standard values are applicable:

Single: All up weight 470 kg (1034 lbs):without airbrakes65 km/h (35 kts) IASwith airbrakes68 km/h (37 kts) IAS

<u>Dual</u>: All up weight 600 kg (1320 lbs): without airbrakes 74 km/h (40 kts) IAS with airbrakes 77 km/h (42 kts) IAS

IV.7 HIGH SPEED FLIGHT

The sailplane shows no flutter tendency within the permissible speed range.

With airbrakes extended in a 45° dive the speed remains below V_{NE} = 280 km/h (151 kts); it goes up to 232 km/h (125 kts) at G = 600 kg.

IV.8 CLOUD FLYING

For min. equipment for cloud flying see II.3 a and II.3 c.

According to past experiences the airspeed indicator system is not exposed to the danger of icing-up. However with strong icing-up the pilot must be always take into account the possible failure of the airspeed indicator. When planning cloud flying, he must take this point into consideration.

Excessive speeds during cloud flying must be avoided in any case. The pilot should try to keep an average speed of about 100 km/h (54 kts) and with increasing speed above 130 km/h (70 kts) he should use the airbrakes in order to control the speed.

Rev.no./Date Sig. Author Date Page no. TN23 Jan.91 Waibel Kaiser April 80 LBA- 26 APP. Attention !! Cloud flying must only be done by pilote having the necessary licence. The legal regulations with regard to airspace and the requirements for instruments have to be met.

IV.9 AEROBATICS

Attention aerobatic flyers !!


Even a sailplane which is approved for full aerobatics does not have infinite strength capacities. Most hazardous are aerobatics which get out of control or are badly executed, as they result in the high loads.

Therefore, it is urgently recommended to have oneself guided by an experienced flight instructor. The ASK 21 being an approved two-seater for full aerobatics offers this possibility.


Such guidance is even prescribed according to \$69 (4) of the German 'LuftPersPO' (Aviation Personnel Test Regulations) dated January 9, 1976. Following \$96 (3) of the said 'LuftPersPO' an adequate experience is required from flight instructors.


Note 11


The normal airspeed indicator system shows a large pressure error in inverted flight during which the airspeed indicator reads 40 km/h (22 kts) too low. When extending the pitot head by attaching a brass tube - 120×1 ; 140mm (5,5 in) in length -, this error disappears. The tube must project in the front at least 70mm (2,75 in). For normal flights this is not necessary. In order to avoid damage when parking the sailplane in the hangar, this tube should not be left on any longer than necessary.





	speeds are recommended :
	Indicated En- Max Acce-
	trance speed leration
Loop upward	single : 155km/h (84 kts) 2 - 3 g dual : 170km/h (92 kts)
Stall Turn	single : 165km/h (89 kts) 3 g dual : 180km/h (97 kts)
Split 'S'	single : 170km/h (92 kts) 2 - 3 g dual : 180km/h (97 kts)
Immelmann	single : 165km/h (89 kts) 2,5-3,5g dual : 180km/h (97 kts)
Slow Roll	single : 150km/h (81 kts) dual : 165km/h (89 kts)
Steep Climbin	
	y)single : 140km/h (76 kts)
Eight)dual : 150km/h (81 kts)
Chandelle	single : 160km/h (86 kts) dual : 175km/h (95 kts)
Permissible I	ndicated Speeds
Inverted flig	ht without pitot head extension :
V _{NE} single dual	65-240 km/h (35-130 kts) 70-240 km/h (38-130 kts)
Indicated man Indicated max	euvering speed V _H = 140 km/h (76 kts) speed V _{NE} = 240 km/h (130 kts)
Inverted fligh	ht with pitot head extension :
Indicated man Indicated max Indicated sta	
28	April 1980 28











ASK 21 - Flight Manual

Attention 11

Never release stick and rudder pedals when flying aerobatics.

With aerobatics instruction a reliable agreement must be made between instructor and student flyer with regard to the communication system for the mutual taking over of the controls.

Airbrakes must be extended as soon as the pilot loses the control of the sailplane or as the speed. increases unvoluntarily too rapidly.

Exception : "Tail sliding" !!

The trim remains in the center position for aerobatic maneuvers. Don't ever change the trim when flying aerobatics !!

PROHIBITED AEROBATICS :

All abrupt aerobatic maneuvers.

Loop forward.

Tail sliding.

ASK 21 - Flight Manual

IV. 10 APPROACH AND LANDING

The most favorable approach speed is about 90 km/h (49 kts). With turbulence it may be advisable to increase the approach speed slightly. Even steep approaches may be slowed down efficiently with the airbrakes. It is advisable to unlock the airbrakes at the beginning of the landing final approach.

Note: The airbrakes increase the stalling speed by about 3 km/h (1,6 knots).

Sideslipping is also suitable as an approach control. With full rudder during sideslipping the rudder pressure decreases to zero; the rudder must be pushed back.

ASK 21 FLIGHT MANUAL

V. RIGGING AND DE-RIGGING

V.1 RIGGING

Rigging the ASK 21 can be carried out by four persons without mechanical assistance, and by three persons with the use of a fuselage stand or a wing support.

Prior to rigging, clean and grease all pins, bolts, bushings and control system connections !

- 1. Set up the fuselage and hold it horizontal.
- Plug the spar fork of the left wing into the fuselage and - if available - place a wing support under the wing end.
- Offer up the right wing and align the main pin fittings.
- 4. Press in the main pins and secure. Never insert the rear wing attachment pins prior to the main pins ?
- 5. Press in the rear wing attachment pins; unscrew the T-tool and check whether the safety lock is engaged.
- 6. Connect and lock the aileron control linkages in the fuselage behind the spar tunnel.You must be able to touch the ball pivot by feeling through the slot in the socket. Also check the proper engagement of the safety lock by pushing it on to close ! Secure them with spring clips!
- 7. Connect and lock the airbrake control linkages in the fuselage behind the spar tunnel. Secure them with spring clips!

TN-No.20 dated 16.10.87

36a

36a

ASK 21 Flight Manual

- 8. The tailplane is fitted onto the fin from the front (see Fig. V.2-1 and V.2-2). Now the Allan bolt at the leading edge is screwed in; this should be screwed in tightly until the spring-loaded safety pin snaps out over the screw head as far as the socket.
- Connect the elevator and safety with a spring clip !

Note, if your glider uses an automatic elevator connection: after cleaning and light-1 v – greasing the plug-in elevator connections, the tailplane is fitted onto the fin both elevator panels must from the front: be fitted into their connectors simultaneously. Then the tailplane is pushed back until the Allan bolt at the leading edge can be screwed in: this should be screwed in tightly until the spring-loaded safety pin snaps out over the screw head as far as the socket.

- Carry out a pre-flight check referring to the Check List.
- 11. The control circuits must be subjected to an operational test.
- Check condition and function of the wheel brake; check the tire pressure.
 See also Section IV.2 Daily Inspections.

Rev.no. Date	Sig.	Author	Date	Pa
TN 22 26.11.9	0 Juw	Ka, Juw	16.10.87	

ASK 21 Flight Manual

V.2 DE-RIGGING

De-rigging is carried out in the reverse sequence to that of rigging. It must be taken care that the rear wing attachment pins have to be removed prior to the main pins.

WARNING: For derigging the horizontal tail from the fin it has to be regarded hat only the method according to Fig. V.2-2 is used.

Fig. V.2-1 WRONG: Twist movement




Fig. V.2-2 RIGHT: Pitch movement



V.3 PARKING

When parking the glider, the canopies have to be closed. When an ASK 21 is parked on an airfield in the sunshine (this must also be observed during the waiting time until take-off when the pilots are already on board) the canopies must not be left open for some time.

Rev.no. Date	Sig.	Author	Date	Page no.
TN 22 26.11.90	Juw	Ka./Juw	16.10.87	37 a

ASK 21 Flight Manual

Depending on the position of the sun and the intensity of the radiation, the burning-glass effect of the canopies can cause a slow fire in the area of the instrument panel or the headrest respectively.

Therefore, if you have to store the glider outside, it is absolutely necessary always to close the canopies and to cover them with a white cloth.

V.4 ROAD TRANSPORT

The design of a glider trailer is another subject and cannot be discussed in all details here. Of course, a closed trailer is preferable. But also an open trailer may serve the purpose, the latter is generally simpler and lighter. It is important that all components are well fixed and have a large support surface.

Structural components survey drawing which can be used for the building of a trailer, can be obtained from ALEXANDER SCHLEICHER.

WARNING: In <u>no case</u> must the elevator actuator fitting be loaded. This fitting trades out of the upper end of the fin. <u>Not even soft</u> foam cushions are allowed. For the construction of the trailer for road transport the full freedone from any load must be carefully regarded.

Rev.no. Date	sig.	Author	Date	Page no.
Rev.no. Date TN 22 26.11.90	Juw	Ka./Juw	16.10.87	37 b

ASK 21 - Flight Manual

V.5 PREVENTIVE MAINTENANCE


The whole surface of the sailplane is painted with a weather resisting, white polyester coat. Impurities may be washed off with a mild cleansing agent. Heavy impurities may be removed with a polish.

For the paint maintenance only silicone-free agents are to be used (e.g. 1 Z-special cleansing agent-D2 from the company W.Sauer & Co., 5060 Bensberg, W. Germany, or the cleansing polish from the company Lesonal). Though the sailplane is rather insensitive, it should be protected as much as possible against moisture and humidity. If water has soaked into any components, these have to be stored in a dry room and must be turned over frequently.

The canopy is best cleaned with a special plexiglass cleansing agent, in an emergency lukewarm water will do. Rewipe only with pure, soft leather or with glove cloth. Never wipe on dry plexiglass.

The safety harnesses must be regularly checked for damage and tears. The metal parts of the harnesses must be checked for corrosion.

ASK 21 - FLIGHT MANUAL



POSITION ERROR


With normal flights the position error of the airspeed indicator is negligible within the whole range up to 280 km/h (151 kts).


With inverted flights the airspeed indicator reads too low, i.e. up to -40 km/h (22 kts).

By attaching an extension tube this error may be eliminated. (see also pages 27/28). The extension tube must project at least 70 mm (2,75 in) past the fuselage nose.

ASK 21 - FLIGHT MANUAL

POLAR





ſ	SHEET: 1 of 1		Technical Note for	Alexander Schleicher GmbH & Co. Segeiflugzeugbau D-6416 Poppenhausen		
	<u>Glider model:</u>	ASW 19, ASW 20/2 ASK 21 ASW 22 ASK 23,	ASK 18B	TN-No. 23 20C/20CL TN-No. 34 TN-No. 21		
	Subject:	New pro and wind	release couplings for aerotow			
verplichten zu Schadener. den Fail der Palentertehung Ler Entragung vorbehalten	<u>Serial number</u> applicability:	ASK 18/: ASW 19/ ASW 20/: ASW 208, ASW 202, ASW 22, ASK 21, ASW 22, ASK 23/: ASH 25,	198, Data Sheet No. 20L, Data Sheet No. 20B1, Data Sheet No. 20CL, Data Sheet No. Data Sheet No. Data Sheet No. 23B, Data Sheet No.	. L-303, all serial no.s . L-314, all serial no.s . L-314, all serial no.s . L-314, all serial no.s . L-339, all serial no.s . L-351, all serial no.s		
dungen techte fur buchsmus	<u>Compliance:</u>		pplicable to new built at of tow release coup	gliders and in case of re- lings.		
Vervielfalligung dieser Unler. Luwderhol Afteilung intes inhalts nicht ausdrucklich zugeslanden ader Gebri	<u>Reason:</u>	According to the company TOST they have stopped the previous production series of the tow release couplings "Nose tow release coupling E 72/75" and "Safety tow release coupling G 72/73". These have been replaced by the new tow release coupling produc- tions series "Nose tow release coupling E 85" and "Safety tow release coupling Europa G 88". In order to guarantee a problem- free exchange of the previous productions series against the new one, the new tow release couplings show externally almost no dif- ferences.				
Weitergabe sowie Verv lage, verwertung und Mit gestattet, soweit nicht au	<u>Action:</u>	 Where replacement is required or where a corresponding installation location is provided the new tow release coupling production series can be installed instead of the previous ones. When this mod is accomplished, a copy of this Technical Note must be inserted as Annex into the Flight and Maintenance Manual of the glider (Operations Manuals respectively). The accomplishment of this action must be entered into the corresponding table in the manuals (the table headline reads: Additions to, Amendments to, Record or Log of Revisions). 				
	<u>Notes:</u>	The glider ou Instructions"	wners must regard the for the new product led by TOST and givin	he "Operating and Maintenance		
	Poppenhausen, January 17, 1990 ALEXANDER SCHLEICHER GmbH & Co. A. Junt z W. Juntow. The German original of this Technical Note has been approved by the LBA under the date of March 1, 1990 (signature: SCHMALDGHANN). The translation into English has been done by best know- ledge and judgement; in any case of doubt the German original is controlling.					
	<u> </u>	· -	·	-		



Airworthiness Directive 1993-001/3

Luftfahrt-Bundesamt

Airworthiness Directive Section Lilienthalplatz 6 38108 Braunschweig Federal Republic of Germany

L'Hotellier ball and socket connectors

Effective Date: April 09, 1998

Affected:

Kind of aeronautical product: Manufacturer: Type: Models affected: Serial numbers affected: German Type Certificate No.: Aircraft L'Hotellier L'Hotellier ball and socket connectors with lock plates ball and socket connectors <u>with lock plates</u> all none

<u>Subject:</u>

L'Hotellier ball and socket connectors with lock plates if installed in sailplanes, powered sailplanes and aeroplanes

Reason:

Reported incidents involving L'Hotellier ball and socket connectors have prompted the LBA to have investigations made as to the operational safety of L'Hotellier ball and socket connectors.

The results have shown that the friction surfaces of the lock plates will be run in and smoothened after a relatively small number of operations. As has been demonstrated in the tests, in this case even normal operating conditions are sufficient under unfavourable circumstances to surmount the static friction (i.e. the lock plates open).

The a.m. airworthiness deficiency may result in inadvertent disconnect of the L'Hotellier ball and socket connectors and thus to considerable operational malfunctions.

Controllability of the aircraft may be affected or even lost so that the defect may lead to an accident.

The reason for the issue of the second edition in April 1994 was the revision of the L'Hotellier Instruction for Maintenance by which the roundness tolerance of the ball was increased from max. 0.05 mm to 0.1 mm.

The ball and socket connectors are to be secured by means of safety pins, Uerlings sleeves or Uerlings type sleeves.

This AD has been issued as a result of several occurrences with Uerlings type sleeves. For well-founded reasons, especially these sleeves are to be inspected for absense of cracks and sufficient self-locking ability and, if necessary, are to be replaced.

Action:

The Luftfahrt-Bundesamt emphacizes the fact that all pilots have to familiarize themselves with the particularities of L'Hotellier connectors, especially with the different locking systems and their handling.

The ball and socket connectors with lock plates are to be secured. For this purpose, the following actions are to be accomplished:

 Safety pins (e.g. L'H 140-31 made by Hotellier), have to be retrofitted, if not yet installed. In certain cases, it may become necessary to rebore the hole in the lock plate, which is provided for visual inspection, to Ø 1.2 mm so that the safety pin can be inserted (see attachment section I).

The use of a safety pin can be waived if the L'Hotellier ball and socket connector is already equipped with an approved locking system (e.g. Uerlings type sleeve, LS locking sleeve, Schempp-Hirth spring or Wedekind locking system) or if such a system is to be installed.

LBA approved locking systems: see attachment section II. Uerlings type sleeves (specification number SE-00I/78) as well as LS locking sleeves can only be used for straight joints and transmissions, but cannot be used for 90° joints.

Inspection of Uerlings Type Sleeves



Airworthiness Directive 1993-001/3

Luftfahrt-Bundesamt

Airworthiness Directive Section Lilienthalplatz 6 38108 Braunschweig Federal Republic of Germany

Inspection of these sleeves for the absence of cracks and sufficient locking force (self-locking ability), replacement of the sleeves, if necessary (see attachment part III).

Installation information:

The sleeves have to be slid axially onto the L'Hotellier ball and socket connector, they may by no means be clipped radially onto the L'Hotellier ball and socket connector. Radial clipping (excessive opening of the sleeve) may lead to cracks or ruptures due to overstressing so that the sleeve cannot function properly any more.

Annual inspection of sleeves :

The sleeves shall be inspected at least once a year for the absence of cracks and sufficient locking force (selflocking ability). In the original specification for the Uerlings sleeves a biannual replacement interval is assumed. Deviations from this provision are stated in the technical information by the manufacturers.

- 2. Flight Manual
- a) Section "Rigging"

The recommendation : "The lock plate of L'Hotellier ball and socket connectors should be secured"... given in several Flight Manuals in the a.m. or in a simular form is to be deleted and to be replaced by the following sentence:

"The L'Hotellier ball and socket connector must be secured."

- b) If older Flight Manuals do not contain information about L'Hotellier ball and socket connectors, section IV (see attachment) is to be included in the Flight Manual under the Section "Rigging", if the L'Hotellier connector is or is to be secured by means of a safety pin. If necessary, the entry is to be included on a new page.
- c) If Uerlings type sleeves are used as additional locking systems for L'Hotellier connectors, section III of the attachment is to be included in the Flight Manual.

These entries in the Flight Manual may be hand-written or inserted as a copy indicating the AD-No. 1993-001/3 in the Flight Manual.

The amendment is to be entered in the list of effective pages indicating the AD-No. 1993-001/3.

3.

Maintenance Manual

The enclosed Instructions for Maintenance (L'Hotellier, issue E 03/94) become herewith part of the operating instructions and are to be included in the aircraft Maintenance Manual - as far as this has not been done already by the manufacturers of the sailplanes, powered sailplanes, and aeroplanes concerned.

4.

All L'Hotellier ball and socket connectors are to be inspected in accordance with the above Instructions for Maintenance. Connectors exceeding the allowable tolerances are to be replaced.

Note:

Type-related technical information already published by the manufacturer or by the product support organisation for L'Hotellier ball and socket connectors become part of this AD.

The safety pins are available from:

- L'Hotellier safety pin, reference no. L'H 140-31
- safety pin Ø 1.2 mm, Ford reference no. 1473 931 (worldwide)
- manufacturers or product support organisations for the sailplane, powered sailplane or aeroplane types concerned

Compliance:

Locking of L'Hotellier connectors:

- on sailplanes and powered sailplanes not later than April 30th, 1994.
- on aeroplanes not later than May 15th, 1998.

Inspection of the Uerlings type sleeves on all aircraft:

Enquiries regarding this Airworthiness Directive should be referred to Mr.Olaf Schneider, Airworthiness Directive Section at the above address, fax-no. 0049 531/2355-254. Please note, that in case of any difficulty, reference should be made to the German issue!



Airworthiness Directive 1993-001/3

Luftfahrt-Bundesamt Airworthiness Directive Section

Airworthiness Directive Section Lilienthalplatz 6 38108 Braunschweig Federal Republic of Germany

With the next annual inspection but not later than May 15th, 1998, and thereafter at least once a year.

Technical publication by the manufacturer:

-none-

Accomplishment and log book entry:

Action to be accomplished by an approved maintenance organisation and to be checked and entered in the log book by a licensed inspector.

Note:

This AD supersedes the AD-No. 1993-001/2 dated April 20, 1994.

Holders of affected aircraft registered in Germany have to observe the following:

As a result of the a.m. deficiencies, the airworthiness of the aircraft is affected to such an extent that after the expiry of the a.m. dates the aircraft may be operated only after proper accomplishment of the prescribed actions. In the interest of aviation safety outweighing the interest of the receiver in a postponement of the prescribed actions, the immediate compliance with this AD is to be directed

Instructions about Available Legal Remedies:


An appeal to this notice may be raised within a period of one month following notification. Appeals must be submitted in writing or registered at the Luftfahrt-Bundesamt, Lilienthalplatz 6, 38108 Braunschweig.

Attachment to Airworthiness Directive No. 1993-001/3 L'Hotellier ball and socket connector, lock plate Attachment page 1 of 4


Section I

L'Hotellier ball and socket connectors with lock plate

If the connectors are not yet equipped with safety pins (e.g. I'H 140-31 made by Hotellier), these safety pins have to be retrofitted. In certain cases it may become necessary to rebore the hole in the lock plate, which is provided for visual inspection, to \emptyset 1.2 mm so that the safety pin can be inserted.



Attachment to Airworthiness Directive No. 1993-001/3 L'Hotellier ball and socket connector, lock plate Attachment page 2 of 4



Attachment to Airworthiness Directive No. 1993-001/3 L'Hotellier ball and socket connector, lock plate Attachment page 3 of 4

Section III Installation instruction for Uerlings type sleeves For installation, the sleeves have to be slid axially onto the l'Hotellier ball and socket connectors. They may by no means be clipped radially onto the l'Hotellier ball and socket connector. Radial clipping (excessive opening of the sleeve) may lead to cracks or ruptures due to overstressing so that the sleeve cannot function properly any more. installation of sleeves connection of controls locked locked and secured

Attachment to Airworthiness Directive No. 1993-001/3 L'Hotellier ball and socket connector, lock plate Attachment page 4 of 4

